

Bothy: Warnscale Head	Assessed by: Denis Mollison	Room: 1 (and only)
Area: Northern England	On: 3 Oct. 2011	Page 1

Room description: 3.4 x 3.2 m, stone walls and floor; ceiling open to roof beams.

Fuller description at: <http://www.ma.hw.ac.uk/~denis/warnscale/descrip.html>

Items to check	Current description	Action required
Doors & windows	Main door with latch. One opening window (approx 60 cm square) and one small non-opening window.	None
Fireplaces & stoves	The one fireplace is of dry-stone construction, unlined, though there has been some external pointing of the flue. Its use is not encouraged, because of the lack of firewood.	Consider fitting stove (non-urgent)
Sources of ignition	None	None
Sources of fuel	None locally	None
Escape route in event of fire	Door or opening window	None
Fire fighting equipment	None	None
Fire detection & alarm equipment	None	None
Fire action plan	None	Seems unnecessary for single room bothy with no particular hazards or impediments.
Other fire safety notices	None	Put up standard bothy fire notice.
Other general action points	---	---

Fire Risk Assessment

FRA1

Mountain Bothies Association

Mountain Bothies Association

A charity registered in Scotland no. SC008685 and a company limited by guarantee and registered in Scotland no. SC191425; website www.mountainbothies.org.uk; registered office: MBA, Henderson Black & Co, Edenbank House, 22 Crossgate, Cupar, Fife, KY15 5HW